#### **OMNICOMM**

# **FAQ**

Frequently Asked Questions 19.02.2025

## Contents

- **3 Contacting Omnicomm Technical Support**
- 3 Issues with Reporting in Omnicomm Online
- 4 Terminal Operation Issues
- 4 LLS Sensor Operation Issues
- 4 Issue with Multiple Products Working Together

## **FAQ**

# **Contacting Omnicomm Technical Support**

When sending a request to Omnicomm Technical Support, please provide the following information, depending on the product:

- 1. Omnicomm Online username
- 2. Terminal ID(s)
- 3. The built-in FW version of the terminal/sensor/display/indicator
- 4. Software versions of products for which the problem occurs (Omnicomm Online, Omnicomm Configurator, Remote Configuration Server)
- 5. The exact date and time when the problem arose
- 6. Time zone
- 7. Problem description: discrepancy between the expected result and the actual result (expected/actual results)
- 9. Client's browser and OS versions
- 10. Photos of the installation location/Screenshots/Downloaded report

#### Issues with Reporting in Omnicomm Online

- 1. Omnicomm Online username
- 2. Terminal ID
- 3. Report name
- 4. The exact date and time when the problem arose
- 5. Time zone
- 6. Problem description: discrepancy between the expected result and the actual result (expected/actual results)
- 7. Client's browser and OS versions
- 8. Screenshot of the report highlighting the problem section
- 9. The downloaded report

#### **Terminal Operation Issues**

- 1. Terminal ID
- 2. Terminal's version of the built-in FW
- 3. Problem description: discrepancy between the expected result and the actual result (expected/actual results)
- 4. Photo of terminal's installation location

Additionally, if the terminal issue appears in the Omnicomm Online report:

- 5. Omnicomm Online username
- 6. The exact date and time when the problem arose
- 7. Time zone
- 8. Screenshot of the report highlighting the problem section

# **LLS Sensor Operation Issues**

- 1. Sensor ID
- 2. Sensor's version of the built-in FW
- 3. Problem description: discrepancy between the expected result and the actual result (expected/actual results)
- 4. Photo of sensor's installation location

Additionally, if the sensor issue appears in the Omnicomm Online report:

- 5. Omnicomm Online username
- 6. ID of the terminal to which the sensor is connected
- 7. Serial number of the sensor connected to the terminal
- 8. The exact date and time when the problem arose
- 9. Time zone
- 10. Screenshot of the report highlighting the problem section

## Issue with Multiple Products Working Together

- 1. Omnicomm Online username
- 2. Terminal name and ID

#### **Contacting Omnicomm Technical Support**

- 3. Sensor name and ID
- 4. Terminal's version of the built-in FW
- 5. Sensor's version of the built-in FW
- 6. Software versions of the products for which the problem occurs
- 7. The downloaded report and its name
- 8. The exact date and time when the problem arose
- 9. Time zone
- 10. Problem description: discrepancy between the expected result and the actual result (expected/actual results)
- 11. Client's browser and OS versions
- 12. Photo of the equipment's installation location
- 13. Screenshot of the report highlighting the problem section

#### **OMNICOMM**

info@omnicomm-world.com www.omnicomm-world.com